

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

09 October 2019

18043-BW Beechwood Elementary / Report Number 002

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Thrash Construction
Date / Time 08 October 2019 / 1:45 PM

Weather / Temp Clear / 71 ° F

Est % Complete 10%

Sched Conformance +/- 00 days

Work in Progress Asphalt Paving at Rear Parking

Present at Site Jason McCoy, Thrash Construction
Central Asphalt
Paul Purser, DBA

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Observations Arriving, I noted paving work in progress. Central Asphalt was installing top layer of asphalt.

I reviewed interior ceiling work at Building 1; demo has continued and grid work has been installed however no ceiling tiles have been installed.

I spoke with Wade Grant who mentioned some speaker wires were inadvertently removed during demo and that the school repaired their sound system during working hours.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Luke Walker (TC)
Chad Shealy / Shaquita Burke (VWSD)
Gary Bailey / Jason Stewart (BPM)
Russ Blount / Shelby Mitchell / Candy Failor (DBA)



Figure 1 – Parking Area Used for Staging



Figure 2 – East Corner Looking West



Figure 3 – Unfinished Paving at South Corner and Existing Sidewalk



Figure 4 – Base Asphalt Paving Layer



Figure 5 – Top Layer and Base Layer Asphalt



Figure 6 – Base Layer Even with Concrete Drain



Figure 7 – Top Layer at West Corner



Figure 8 – Top Layer Even with Sidewalk



Figure 9 – Undisposed Excavated Drain Pipe



Figure 10 – North Corner of Parking Looking SE



Figure 11 – Undisposed Formwork at Dumpster Slab



Figure 12 – Ceiling Material



Figure 13 – New Paving Even with Existing Paving



Figure 14 – Starting West Corner of Building 1 – First Classroom at Interior Entry



Figure 15 – West Corner of Building 1 – 2nd Class



Figure 16 – West Corner of Building 1 – 3rd Class



Figure 17 – South Corner of Building 1 – 4th Class



Figure 18 – South Corner of Building 1 – 5th Class



Figure 19 – South Corner of Building 1 – 6th Class



Figure 20 – Entry from Southeast Side of Building 1



Figure 21 – East Corner of Building 1 Hall Area



Figure 22 – Existing Furr Down Structure (Typical)



Figure 23 – East Corner of Building 1 – 7th Class



Figure 24 – East Corner of Building 1 – 8th Class



Figure 25 – North Corner of Building 1 – 10th Class



Figure 26 – North Corner of Building 1 – 11th Class



Figure 27 – North Corner of Building 1 – 12th Class



Figure 28 – North Corner of Building 1 – Hall Area



Figure 29 – North Corner of Building 1 – Entry Hall from Interior



Figure 30 – Misaligned light with Framework



Figure 31 – Unfinished Grid Corners