

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

16 April 2020

18044-Bovina Elementary / Report Number 008

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 15 April 2020 / 10:30 AM
Weather / Temp Sunny / 59 ° F
Est % Complete 25%
Sched Conformance + 00 days
Work in Progress Dirt work

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Richard Creel, Paul Jackson & Son
Larry Knight, Paul Jackson & Son
Paul Purser, DBA

Observations Arriving on site, I made my way to the area that our addition that is to be located. Dirt has been dug up for drying; also, 2 drains have been removed to the extents of the work are.

I made my way through the school to note any other changes; the area on the southern wall that was noted to have termite damage has been uncovered. There appears to be more damage further up the wall but it has not been uncovered. The lower section of the wall is made of material that is impervious to termites, however the above section is unknown at the point but does appear to have a wood base plate supported at 30-36" center to center atop the masonry lower wall. This base plate shows termite damage.

Floor demo has been complete, aside from the mech/elec room.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Jerry Montgomery (SM)



Figure 1 – North Addition Dirt Work



Figure 2 – Drain at Extent of Project Bounds



Figure 3 – Drain that Moves Below Building Footing



Figure 4 – Excavation Depth



Figure 5 – Southern Wall Paneling Removed @ Classroom 4



Figure 6 – Termite Damage @ Base Plate



Figure 7 – Note Shims Under Base CC ~36"



Figure 8 – North Hall Demo Complete (typical class)