

## Architect's Field Report

T. Doug Dale, AIA

Jeffrey R. Barnes, AIA

Leigh G. Jaunsen, AIA, LEED AP

Russ S. Blount, AIA, LEED  $\,$  AP

Jason M. Agostinelli, AIA

In memory of Michael A. Barranco, AIA 1962-2011 26 May 2021

15094 Community Bank Headquarters

Contract Fountain Construction Company, Inc.

Date / Time 25 May 2021 / 12:00 PM

Weather / Temp Sunny / 83 ° F

Present at Site Stan Green, FCC

Masons, Mechanical Installers, Drywall Finishers

Paul Purser, Dale Partners Architects

Observations Arriving on site, I met Stan Green at the job site trailer. He mentioned

work was moving forward with storefront installations in select parts of the façade. Also, he has had issues with the sealant contractor's schedule. He mentioned that the crane is in place for the erection of the precast at the drive thru and that they attempted to set panels last week

but due to high winds were unable.

Inside, drywall installers were still at work as well as mechanical

installers.

Items to Verify None.

Action Required None.

Report By:

Paul Purser, AIA, Architect Dale Partners Architects, P.A.

cc: Jim White, Community Bank

Ryan Puckett, Community Bank

Russ Blount, AIA, Dale Partners Architects Brad Fountain, Fountain Construction Robert Clay, Fountain Construction

DALE PARTNERS ARCHITECTS, P.A.

Architecture = Interiors = Planning

One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100

P 601.352.5411 • f 601.352.5362

161 Lameuse Street, Suite 201 Biloxi, MS 39530

P 228.374.1409 • f 228.374.1414

dalepartners.com



Figure 1 – Continued work on south elevation



Figure 2 – NW Corner, reworked



Figure 3 – Work at Precast Panel NE Corner



Figure 4 – NE Corner Brick Offset



Figure 5 – SE Brick work at Corner



Figure 6 – Double Height Stair Space is Shaping Up



Figure 7 –  $3^{rd}$  Floor Break Room; GlasRoc installed at cabinet wall




Figure 8 – Upper Floor Progress