

Architect's Field Report

T. Doug Dale, AIA

Jeffrey R. Barnes, AIA

Leigh G. Jaunsen, AIA, LEED AP

Russ S. Blount, AIA, LEED AP

Jason M. Agostinelli, AIA

In memory of
Michael A. Barranco, AIA
1962-2011

17 June 2021

15094 Community Bank Headquarters

Contract Fountain Construction Company, Inc.

Date / Time 17 June 2021 / 1:00 PM

Weather / Temp Sunny / 90 ° F

Present at Site Masons, Mechanical Installers, Drywall Finishers, Electricians, Framers
Paul Purser, Dale Partners Architects

Observations On site, workers have removed the upper portion of paneling at the drive thru steel in order to brace steel according to engineers' drawings. Sealant workers were installing sealant and back rod at west façade. Concrete workers were pouring around sewer manhole at northwest corner of the site.

At the interior, workers were busy at the 1st and 4th floors installing framing and drywall.

Items to Verify None.

Action Required None.

Report By: Paul Purser, AIA, Architect
Dale Partners Architects, P.A.

cc: Jim White, Community Bank
Ryan Puckett, Community Bank
Russ Blount, AIA, Dale Partners Architects
Brad Fountain, Fountain Construction
Robert Clay, Fountain Construction

DALE PARTNERS ARCHITECTS, P.A.

Architecture • Interiors • Planning

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100

P 601.352.5411 • f 601.352.5362

161 Lameuse Street, Suite 201
Biloxi, MS 39530

P 228.374.1409 • f 228.374.1414

dalepartners.com



Figure 1 – Drive Thru Progress



Figure 2 – Sealant Work is Ongoing



Figure 3 – Concrete Work at Site



Figure 4 – North Façade Progress



Figure 5 – Bank Window Room Progress



Figure 6 – Progress at 3rd Floor



Figure 7 – Uncovered Ducting at 4th Floor



Figure 8 – Drywall Installers at 4th Floor