DALE PARTNERS

Architect's Field Report

15094 Community Bank Headquarters

28 June 2021

T. Doug Dale, AIA Jeffrey R. Barnes, AIA Leigh G. Jaunsen, AIA, LEED AP Russ S. Blount, AIA, LEED AP Jason M. Agostinelli, AIA

> In memory of Michael A. Barranco, AIA 1962-2011

Contract	Fountain Construction Company, Inc.
Date / Time	25 June 2021 / 4:30 PM
Weather / Temp	Sunny / 90 ° F
Present at Site	Drywall Finishers & Framers Paul Purser, Dale Partners Architects
Observations	Progress has been made at the drive thru area. Panels have been reset and bracing added to steel structure.
	At the interior, framing is ongoing at the lower and upper levels. Drywall workers were at the 4 th floor finishing and installing gypsum.
Items to Verify	None.
Action Required	None.
Report By:	Paul Purser, AIA, Architect Dale Partners Architects, P.A.

CC:

Jim White, Community Bank Ryan Puckett, Community Bank

Ryan Puckett, Community Bank Russ Blount, AIA, Dale Partners Architects Brad Fountain, Fountain Construction Robert Clay, Fountain Construction

DALE PARTNERS ARCHITECTS, P.A.

Architecture - Interiors - Planning

One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100

P 601.352.5411 • f 601.352.5362

161 Lameuse Street, Suite 201 Biloxi, MS 39530

P 228.374.1409 **=** f 228.374.1414

dalepartners.com



Figure 1 – Drive Thru Progress




Figure 2 – Bracing at Drive Thru Panel



Figure 3 – Bracing at Drive Thru Panel



Figure 4 – Masonry work at the South Elevation is Ongoing




Figure 5 – Framing Progress at the First Floor



Figure 6 – Framing at the 4th Floor



Figure 7 – Framing, Insulation, & Drywall Ongoing at the 4th Floor



Figure 8 – Framing, Insulation, & Drywall Ongoing at the $4^{th}\,\text{Floor}$




Figure 9 – Framing, Insulation, & Drywall Ongoing at the $4^{th}\,\text{Floor}$




Figure 10 – Drywall Progress at 4th Floor