

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

16 October 2019

18043-BW Beechwood Elementary / Report Number 004

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Thrash Construction  
Date / Time 15 October 2019 / 4:30 PM  
Weather / Temp Rain / 70 ° F  
Est % Complete 10%  
Sched Conformance +/- 00 days  
Work in Progress None

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site Paul Purser, DBA

Observations Arriving on site, Rain began in earnest. I walked interior for Building 1. Most Demo has been performed save a couple of rooms.

Where 2x2 Ceilings have been reinstalled, audio tiles have not been refitted around audio equipment.

At the most Southern Corner room, there is a leak but the 2x2 ceiling has not been reinstalled.

At the most Eastern Corner room, there is also a leak but the 2x2 tile has been reinstalled and is now damaged.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner  
Dale | Bailey, an Association

cc: Luke Walker (TC)  
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Shelby Mitchell / Candy Failor (DBA)  
Blake Mendrop (M)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)



Figure 1 – Entry Hall South



Figure 2 – Administration Office



Figure 3 – Teacher Area



Figure 4 – Hanging Wire



Figure 5 – Southwest Main Hall



Figure 6 – Off Center Lighting




Figure 7 – Proper Alignment of Lighting



Figure 8 – Unfinished Audio Installation



Figure 9 – Off-Center Lighting



Figure 10 – Leak in South Corner Classroom



Figure 11 – Angled Lighting (Needs Adjustment)



Figure 12 – Note Gap Between Light and Tiles is more on Left than Right



Figure 13 – New Grid On North Side of Main Hall



Figure 14 – Leak at East Corner Classroom





Figure 15 – Lighting Off alignment by 3- inches



Figure 16 – Offset Lighting



Figure 17 – Example of Room Demoed with New Grid Installed



Figure 18 – Grid Installation Missing Corner