

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

25 October 2019

18043-BW Beechwood Elementary / Report Number 006

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Thrash Construction
Date / Time 24 October 2019 / 4:00 PM
Weather / Temp Clear / 73 ° F
Est % Complete 10%
Sched Conformance +/- 00 days
Work in Progress None

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site School Receptionists
Paul Purser, DBA

Observations Arriving on site, I spoke with the receptionist and was told some work has begun in building number 3. I walked building number 2 first and then walked building 3.

I noted progress in the building number 1. Tiles in the southern most classroom have been installed and damaged due to previously noted roof leak.

Demolition in building has followed every other room demo recommendation for 2 rooms so far (314 & 312).

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Luke Walker (TC)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Shelby Mitchell / Candy Failor (DBA)
Blake Mendrop (M)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Damage at Upper Drywall & No Corner In Place



Figure 2 – Example of Curved Grid Corner



Figure 3 – Demo at Bathrooms




Figure 4 – Low Hung Light



Figure 5 – Water Damaged Tile at Room 111



Figure 6 – Demo and Put Back at Dining 117



Figure 7 – Properly Aligned Lighting



Figure 8 – Properly Aligned Lighting



Figure 9 – Damage at Newly Installed Curved Corner Near Work Room 109A



Figure 10 – Corner not Continuous Corridor 127



Figure 11 – Drywall Damage at Upper Wall Corridor 127



Figure 12 – Demo in Building 3 Room 314



Figure 13 – Demo in Building 3 Room 312