

## Architect's Field Report

201 Park Court, Suite B

20 November 2019

Date / Time

Ridgeland, MS 39157

18043-BW Beechwood Elementary / Report Number 010

P 601.790.9432 F 888.281.0547

Contract **Thrash Construction** 

19 November 2019 / 3:40 PM

One Jackson Place, Suite 250

Clear / 74 ° F Weather / Temp

188 East Capitol Street

Jackson, MS 39201-2100

Est % Complete

25%

P 601.352.5411

Sched Conformance +/- 00 days

F 601.352.5362

Work in Progress None

161 Lameuse Street, Suite 201

Present at Site

Observations

**School Receptionists** 

Biloxi, MS 39530

Paul Purser, DBA

Arriving, I walked Building 1 to note any changes and saw none.

P 228.374.1409

I walked Building 3. Progress with Demolition and Reinstallation

continues at an appropriate rate. Some item on reinstallation have not been completed (see figure 1, 2, 4, & 5).

F 228.374.1414

I also spoke with Ms. Donna Smith in Room 302 who mentioned that a 12" piece of rebar had fallen on her computer equipment. She says that no damage was made. On inspection of where it possibly could have fell from, I noted a pipe hanger that appears to have been installed

originally, but has since been disconnected (see figure 7).

Items to Verify

Confirm Pipe Hanger was not in Use Prior to Demo and does not require

reinstallation (Figure 7).

**Action Required** 

None

Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Shelby Mitchell / Candy Failor (DBA)

Blake Mendrop (M)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Building 3 Hall




Figure 2 – Building 3 Cafeteria Unfinished Registers



Figure 3 – Building 3 Cafeteria Notch Showing @ Light




Figure 4 – Building 3 Cafeteria Unfinished Registers



Figure 5 – Building 3 Cisco Router (What's the plan here?)



Figure 6 – Typical Grid Put Back Building 3



Figure 7 – Pipe Hanger Not In use



Figure 8 – Typical Demo in Building 3



Figure 9 – Typical Finished Ceiling in Building 3