

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

13 December 2019

18043-BW Beechwood Elementary / Report Number 013

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Thrash Construction
Date / Time 11 December 2019 / 3:10 PM
Weather / Temp Clear / 54 ° F
Est % Complete 30%
Sched Conformance +/- 00 days
Work in Progress none

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site School Staff
Paul Purser, DBA

Observations Arriving on site, I walked building 1 first to check on work. High ceilings have tiles removed.

Building 2 Art class room has been installed, also. There is some corner grid in this room around the skylight that has not been replaced and looks unsightly.

In building 3, high ceiling grid has been removed.

Items to Verify Plan for corner grid in Art Class (building 2)

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Luke Walker (TC)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Shelby Mitchell / Candy Failor (DBA)
Blake Mendrop (M)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Building 2 Corridor



Figure 2 – Building 2 Art Class (rust on old grid)



Figure 3 – Janitor Room @ 100D in building 1 (no ACT)



Figure 4 – Building 1 Tile Removed



Figure 5 – Building 1 Tile Removed



Figure 6 – Lifts stored on Site



Figure 7 – Building 3 (grid removed)



Figure 8 – Building 3 (grid removed)



Figure 9 – Double Gate Re-Installed



Figure 10 – Double Gate Re-Installed