

Architect's Field Report

201 Park Court, Suite B	16 January 2020	
Ridgeland, MS 39157 P 601.790.9432	18043-BW Beechwood Elementary / Report Number 017	
F 888.281.0547	Contract	Thrash Construction
One Jackson Place, Suite 250	Date / Time	15 January 2020 / 5:15 PM
188 East Capitol Street	Weather / Temp	Drizzle / 70 ° F
Jackson, MS 39201-2100	Est % Complete	58%
P 601.352.5411	Sched Conformance	+/- 00 days
F 601.352.5362	Work in Progress	None
161 Lameuse Street, Suite 201	Present at Site	School Staff Paul Purser, DBA
Biloxi, MS 39530	Observations	Arriving, I walked building 1 to 3 in succession. I noted some work
P 228.374.1409		performed in vestibules in preparation for FRP install.
F 228.374.1414		The Gym floor was in use.
		Vestibule Resinous Flooring Cleanup Issues still need attention.
	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC) Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Shelby Mitchell / Candy Failor (DBA) Blake Mendrop (M) Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Library Ceiling Installed



Figure 2 – Library Auxiliary Room



Figure 3 – Primed Panels to Received FRP @ Building 1 Vestibule



Figure 4 – Building 1 Janitor's Closet Ceiling



Figure 5 – High Ceiling Vents in Building 1




Figure 6 – Corridor in Building 1




Figure 7 – Primed Panels to Received FRP @ Building 3 Vestibule



Figure 8 – Fire Alarm Installed in Vestibule Building 3



Figure 9 – Some Vents still to Paint