

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

12 February 2020

18043-BW Beechwood Elementary / Report Number 021

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Thrash Construction  
Date / Time 11 February 2020 / 3:00 PM  
Weather / Temp Drizzle / 50 ° F  
Est % Complete 71%  
Sched Conformance +/- 00 days  
Work in Progress 3<sup>rd</sup> Party Fire Alarm Testing

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site School Staff  
Inspection Crew  
Dave Newby, Moses Electric  
Paul Purser, DBA

Observations I arrived on site with the main purpose of marking light lens for the contractor so that they knew which to replace. During this task, I noticed a few light fixtures that were not in order. I also noticed that grilles were not at the ceiling in a couple of smaller spaces off of room 200.

Items to Verify HVAC Grilles for Auxiliary Spaces at Room 200

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner  
Dale | Bailey, an Association

cc: Luke Walker (TC)  
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Shelby Mitchell / Candy Failor (DBA)  
Blake Mendrop (M)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)



Figure 1 – Light Needs Adjusting in 210A



Figure 2 – Light Needs Adjusting in 304