

Architect's Field Report

201 Park Court, Suite B

19 February 2020

Ridgeland, MS 39157

18043-BW Beechwood Elementary / Report Number 022

P 601.790.9432 F 888.281.0547

Contract **Thrash Construction**

18 February 2020 / 3:12 PM

One Jackson Place, Suite 250

Weather / Temp

Date / Time

Overcast / 73 ° F

188 East Capitol Street Jackson, MS 39201-2100

Est % Complete 71%

Sched Conformance +/- 00 days

P 601.352.5411 F 601.352.5362

Work in Progress

None

161 Lameuse Street, Suite 201

School Staff

Present at Site

Biloxi, MS 39530

Paul Purser, DBA

P 228.374.1409 F 228.374.1414 Arriving on site, I reviewed progress. Lenses have been swapped out as

marked last week. Some lights are crooked this week that were not

before in Corridor Space.

Items to Verify

Observations

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Shelby Mitchell / Candy Failor (DBA)

Blake Mendrop (M)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Crooked Lights in Corridor Near Room RM 110




Figure 2 – Crooked Lights in Corridor Near Room RM 110



Figure 3 – Tape on FRP from install