

Architect's Field Report

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	26 February 2020	
	18043-BW Beechwood Elementary / Report Number 023	
	Contract	Thrash Construction
One Jackson Place, Suite 250	Date / Time	25 February 2020 / 3:20 PM
188 East Capitol Street	Weather / Temp	Sunny and clear / 63 ° F
Jackson, MS 39201-2100	Est % Complete	71%
P 601.352.5411	Sched Conformance	+/- 00 days
F 601.352.5362	Work in Progress	None
161 Lameuse Street, Suite 201	Present at Site	School Staff Paul Purser, DBA
Biloxi, MS 39530	Observations	Arriving on site, I spoke with receptionists. She mentioned that the smell
P 228.374.1409		from the epoxy floor installations was causing issues to people with asthma and a pregnant teacher. She requested that flooring install to
F 228.374.1414		happen at the beginning of the week end.
		I reviewed installation of epoxy. For the most part it looked good, however, there are some repairs needed: I noted in images below.
	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC) Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Shelby Mitchell / Candy Failor (DBA) Blake Mendrop (M) Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Building 3 Boys Room



Figure 2 – Corner Cut In's Look Good



Figure 3 – Paint Over Door Stop (typical)




Figure 4 – Building 3 Girls



Figure 5 – Building 2 Gym (T06): discolored drips evident after install



Figure 6 – T06



Figure 7 – T06: debris left embedded in Epoxy



Figure 8 – Painted Door Stops



Figure 9 – Additional Coat Required in T06 for Full Coverage



Figure 10 – Additional Coat Required in T06 for Full Coverage



Figure 11 – Additional Coat Required in T06 for Full Coverage



Figure 12 – Paint on Drain Cover in T06



Figure 13 – Paint on Threshold in T06



Figure 14 – Girls Bathroom in Building 1 (Paint on Partitions Existed Before Install)