

## Architect's Field Report

201 Park Court, Suite B

11 March 2020

Ridgeland, MS 39157

18043-BW Beechwood Elementary / Report Number 025

P 601.790.9432

F 888.281.0547 Contract **Thrash Construction** 

One Jackson Place, Suite 250

11 March 2020 / 1:26 PM

188 East Capitol Street

Date / Time

Weather / Temp Sunny and clear / 74 ° F

Jackson, MS 39201-2100

Est % Complete

71%

P 601.352.5411

Sched Conformance +/- 00 days

F 601.352.5362

Work in Progress

VCT Floor Install & Prep

**VCT Install Crew** 

Present at Site

Paul Purser, DBA

161 Lameuse Street, Suite 201 Biloxi, MS 39530

Observations

P 228.374.1409 F 228.374.1414 I arrived on site and saw that work on flooring was ongoing. Building 3 Cafeteria is the only section where install has started of final product.

Building 2 and 3 floors have been prepped however. Demo in lobby

areas has been performed.

Items to Verify

None

**Action Required** 

None

Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Shelby Mitchell / Candy Failor (DBA)

Blake Mendrop (M)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education




Figure 1 – Door Cut for Floor Overlay



Figure 2 – Floor Prep at Entry (vct sanded and leveling compound added)




Figure 3 – Vestibule @ Building 3



Figure 4 – Entry Lobby Ceiling Removed



Figure 5 – Wall Prep Begun



Figure 6 – New VCT Install Ongoing in Building 3 Cafeteria



Figure 7 – Stair in Building 3 Exterior and Balusters Painted




Figure 8 – Stair in Building 3 Exterior and Balusters Painted



Figure 9 – Hall in Building 2 Prepped



Figure 10 – Wall Prep Begun



Figure 11 – Lobby @ Building 1 Ceiling Demoed




Figure 12 – Building 1 Stair Work