

06 May 2020

18043-BW Beechwood Elementary / Report Number 033

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	Contract	Thrash Construction
	Date / Time	05 May 2020 / 11:00 AM
	Weather / Temp	Overcast / 74 ° F
	Est % Complete	90%
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Sched Conformance	+/- 00 days
	Work in Progress	Caulking at Sidewalks
	Present at Site	Zach Jennings, Trash Construction Paul Purser, DBA
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Observations	Arriving on site, I reviewed interior and exterior work. I noted rubber treads have been corrected with missing items, however, the new rubber installed is not evenly adhered to the step which may be forthcoming, but I wanted to be sure that this was not the final installation.  I noted in the main hall for building 2 that there is a door dragging on the new floor that should be undercut to fit floor overlay.  At the exterior sidewalk work is ongoing. Playground ramps have been installed.
	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP, Partner  
Dale | Bailey, an Association

cc: Luke Walker (TC)  
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Shelby Mitchell / Candy Failor (DBA)  
Blake Mendrop (M)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)



Figure 1 – Rubber Face is Not fully adhered to Step and appears wavy



Figure 2 – Door dragging in hall needs undercut





Figure 3 – Panels Painted



Figure 4 – This light in Building 3 has a gap on 2 corners and is not flush with ceiling





Figure 5 – Ramps installed



Figure 6 – Ramps Secured





Figure 7 – Can we fill this recess with a Cementitious material and repair this void?



Figure 8 – The drywall at this window Jamb needs patching in Building 1 Lobby