

## Architect's Field Report

201 Park Court, Suite B

20 June 2020

Date / Time

Ridgeland, MS 39157

18044-Bovina Elementary / Report Number 016

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

18 June 2020 / 12:30 PM

One Jackson Place, Suite 250

161 Lameuse Street, Suite 201

Weather / Temp Clear / 86 ° F

188 East Capitol Street

Est % Complete 27%

Jackson, MS 39201-2100

2170

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress Masonry Installation

Floor Preparation

VCT Installation Painting

Biloxi, MS 39530

Present at Site

Richard Creel, Paul Jackson & Son

P 228.374.1409

Paul Purser, DBA

F 228.374.1414 Observations

Arriving on site, I entered the site through the North Hall Entry from our

new addition. Paint work is ongoing in the existing hall and flooring

installers are working there way here.

Masons were working in the bathrooms, finishing up block work, as the contractor is working towards completion of bathrooms before school

start.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Jerrry Montgomery (SM)

dalepartners.com

baileyarch.com Architects Who Know Education



Figure 1 – New Entry @ Workroom 25



Figure 2 – Interior Header at New Entry @ Workroom 25



Figure 3 – Paint Work is Ongoing



Figure 4 – Block Work at Boys T5



Figure 5 – NEW VCT at North side Classrooms of South Hall




Figure 6 – Block Work at Girls T6




Figure 7 – Block Work at Boys T1



Figure 8 – Block Work at Girls T9




Figure 9 – Block Work at Girls T9 (Ceiling Grid will Require edge Support at Ceiling/Wall)



Figure 10 – Block Work at Boys T10