

Architect's Field Report

201 Park Court, Suite B

21 July 2020

Ridgeland, MS 39157

18044-Bovina Elementary / Report Number 020

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

Date / Time

21 July 2020 / 10:30 AM

One Jackson Place, Suite 250

Weather / Temp

Clear / 88 ° F

188 East Capitol Street Jackson, MS 39201-2100

Est % Complete 30%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Tile Install

Work in Progress

Partition Install

161 Lameuse Street, Suite 201

Present at Site

Larry Knight, Paul Jackson & Son

Biloxi, MS 39530 P 228.374.1409 Paul Purser, DBA

F 228.374.1414

Observations

Arriving on site, I entered thru the front. VCT work has been completed in the Auditorium. As I moved along through the corridors, I also saw that VCT work in the North Corridor has been installed but not waxed. Tile in the bathrooms off of this hall is ongoing and about 75% complete.

At the exterior, roofers have installed edge trim and gutter work is

beginning.

I entered through the West Entry at the cafeteria where movers were emptying the space. I met Larry Knight, PJS, at the girl's restroom on this south hall. He was installing toilet partitions, which have been competed

in the boy's restroom.

Tile has been completed in these restrooms. Pay attention to figures 15

& 16 in this report as this trim is not correctly seated in the tile.

Items to Verify

Action Required

Reset Metal trim for flush appearance with tile.

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Jerrry Montgomery (SM)

dalepartners.com baileyarch.com

Architects Who Know Education




Figure 1 – Steel Frame Installed at Auditorium




Figure 2 – VCT installed and Waxed at Auditorium



Figure 3 – North Hall VCT




Figure 4 – North Hall VCT




Figure 5 – Marble Threshold Installed




Figure 6 – Tile at Wet Wall




Figure 7 – Tile at Wet Wall



Figure 8 – Tile at Wet Wall




Figure 9 – Tile Set



Figure 10 – New Metal Edge Trim & Downspout ready to install




Figure 11 – Toiler Partition Installation



Figure 12 – Toiler Partition Installation




Figure 13 – Toiler Partition Installation



Figure 14 – Tile at Urinal Wall




Figure 15 – Edge Trim Protrudes 1/8" +/-



Figure 16 – Edge Trim Protrudes 1/8" +/-