

Architect's Field Report

201 Park Court, Suite B

27 August 2020

Date / Time

Ridgeland, MS 39157

18044-Bovina Elementary / Report Number 022

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

26 August 2020 / 2:30 PM

One Jackson Place, Suite 250

Weather / Temp

Partly cloudy / 90 ° F

188 East Capitol Street Jackson, MS 39201-2100

Est % Complete 74%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress Decking

Present at Site 161 Lameuse Street, Suite 201

Richard Creel, Paul Jackson & Son Paul Purser, DBA

Biloxi, MS 39530 P 228.374.1409

F 228.374.1414

Observations

I pulled around the main building to the rear addition when I arrived. I

met Mr. Richard Creel at the Job Site Trailer. His crew was just finishing

up decking at the roof and pulling off.

Inside the existing buildings, restroom work is ongoing. Focus has been

paid to toilet room t-3. Finishes are installed here but not fixtures.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS) Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Candy Failor (DBA) Brandon McKay / Austin Newell (WGK) Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

Jerrry Montgomery (SM)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – On-going build at Addition



Figure 2 – Decking Partially Installed



Figure 3 – Brick Mockup and example of Air Gap



Figure 4 – Roof Edge at North Side of Building



Figure 5 – Exterior Rock Partially Installed



Figure 6 – Water-Proofing Partially Installed




Figure 7 – Roof Edge



Figure 8 – Decking Partially Installed



Figure 9 – Roofing Installed




Figure 10 – Toilet Paper Towel Holders Installed




Figure 11 – Finishing Still Needed at top of Walls



Figure 12 – Caps Required at Wall Tops



Figure 13 – Missing Urinal Installed



Figure 14 – Outlet Covered




Figure 15 – Closer Opens Approx. 70 degrees



Figure 16 – Door Panels Installed