

06 May 2020

Weather / Temp

18045-BOW Bowmar Elementary / Report Number 004

201 Park Court, Suite B

Ridgeland, MS 39157

P 601.790.9432

F 888.281.0547

One Jackson Place, Suite 250

188 East Capitol Street

Jackson, MS 39201-2100

P 601.352.5411

F 601.352.5362

Present at Site

161 Lameuse Street, Suite 201

Biloxi, MS 39530 P 228.374.1409

F 228.374.1414

Paul Jackson & Son Contract

Date / Time 05 May 2020 / 12:00 PM

Overcast / 76 ° F

Est % Complete 10%

Sched Conformance +/- 00 days

Concrete Demo Work in Progress

> Interior Ceiling Demolition Window Refinishing

James Brock, Paul Jackson & Son

Demo Crews Paul Purser, DBA

Observations I entered the site from the Main front entry. Noting work performed in

> the auditorium, I reviewed further demo work in the hall areas. I met James Brock as he was refinishing interior steel frames of windows in Classroom 15. We discussed work in this area already performed.

> Mr. Brock and I also walked Corridor 115 and reviewed issues with step down in roof that may prevent ducting from being run down the hallway

as per plans.

We walked to the exterior and noted demo work on trailers is complete

aside from cleanup. Concrete demo is being performed in this area at

the North Section of courtyard.

Items to Verify

Action Required

Report By:

None

None

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education




Figure 1 – Chairs in Auditorium have been unfastened at floor



Figure 2 – Demo work at Hallway




Figure 3 – Demo work at Hallway



Figure 4 – Demo work at Hallway



Figure 5 – Classroom 15 plastic protection & window refinishing



Figure 6 – Step down at Roof




Figure 7 – Pipe prevent duct runs from crossing each other



Figure 8 – Courtyard Demo



Figure 9 – Courtyard Demo



Figure 10 – Concrete Demo Ongoing




Figure 11 – Corridor 100 Demo Ongoing




Figure 12 – Corridor 100 Demo Ongoing