

28 May 2020

18045-BOW Bowmar Elementary / Report Number 007

201 Park Court, Suite B

Contract

Paul Jackson & Son

Ridgeland, MS 39157

Date / Time

27 May 2020 / 2:30 PM

P 601.790.9432

Weather / Temp

Clear / 82 ° F

F 888.281.0547

Est % Complete

15%

One Jackson Place, Suite 250

161 Lameuse Street, Suite 201

Sched Conformance

+/- 00 days

188 East Capitol Street

Work in Progress

Plumbing Interior Demo

Jackson, MS 39201-2100

Present at Site

Paul Purser, DBA

P 601.352.5411 F 601.352.5362

Observations

I arrived on site and walked through the entry at the passage 117. The building had a very strong chemical smell which I can assume was from the stripper being used to remove paint at the windows. Only 2 workers

were in the building applying the stripper and removing paint.

Plumbers were in the rear courtyard working our drain pipe.

Biloxi, MS 39530

P 228.374.1409

F 228.374.1414 **Action Required** None None

Report By:

Items to Verify

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

James Brock / Jimmy White (PJS)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Rough In Plumbing



Figure 2 – Rough In Plumbing



Figure 3 – Grate Surrounded by Sediment Protection



Figure 4 – Chemical Stripper Used to Remove Paint