

04 June 2020

18045-BOW Bowmar Elementary / Report Number 008

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Contract	Paul Jackson & Son
Date / Time	04 June 2020 / 9:00 AM
Weather / Temp	Cloudy / 83 ° F
Est % Complete	15%
Sched Conformance	+/- 00 days
Work in Progress	Paint Prep Window Rehabilitation
Present at Site	Jimmy White, Paul Jackson & Son Paul Purser, DBA
Observations	Arriving on site, I noted that asbestos protection has been installed and that negative pressure venting was in place. Work has been performed removing insulation at piping where required. Finishers were in the West Hall Classrooms repairing plaster. In the rear yard, storm drainage has been installed and inlets set. Grading stakes have also been laid out. Window Rehabilitation was ongoing in this area.
Items to Verify	None
Action Required	None
Report By:	

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)
Tom Schaeffer / Will Grigg (M)
Kevin Starks / Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Asbestos Protection Installed with Signage



Figure 2 – Secondary Asbestos Plastic Protection



Figure 3 – Asbestos Insulation Removal @ Pipe



Figure 4 – Asbestos Protection between Halls



Figure 5 – Inlet Installed with Storm Drainage



Figure 6 – Grading Stakes Set



Figure 7 – Window Glazing Removal



Figure 8 – Chemical Stripper Used to Remove Paint



Figure 9 – Paint and Prep Ongoing



Figure 10 – Demoad Concrete in South Corner of Rear Yard