

26 June 2020

18045-BOW Bowmar Elementary / Report Number 009

201 Park Court, Suite B

Contract

Paul Jackson & Son

Ridgeland, MS 39157

Date / Time

24 June 2020 / 1:45 PM

P 601.790.9432

Weather / Temp

Cloudy / 80 ° F

F 888.281.0547

Est % Complete

15%

One Jackson Place, Suite 250

Sched Conformance

+/- 00 days

188 East Capitol Street

Work in Progress

Duct Install Window Rehabilitation

Jackson, MS 39201-2100

Present at Site

Paul Purser, DBA

P 601.352.5411 F 601.352.5362

Observations

Upon arrival, I entered through the Main entry. Asbestos remediation is ongoing in the Main Hall running North and South. Chairs have been removed in auditorium and window rehab was ongoing in this area.

In the hall running east/west, electricians were installing new conduit.

161 Lameuse Street, Suite 201

Biloxi, MS 39530

P 228.374.1409

F 228.374.1414

Mechanical ducting has been installed in this area as well.

Items to Verify **Action Required** None None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

James Brock / Jimmy White (PJS)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Library 43 Window Uncovered



Figure 2 – Window Sill at Library 43



Figure 3 – Window Rehabilitation in Auditorium




Figure 4 – Chairs in Auditorium Removed




Figure 5 – New Ducting in Passage 116



Figure 6 – New Ducting in Passage 116



Figure 7 – Pad in Rear Yard



Figure 8 – Primed Lockers