

02 December 2020

18045-BOW Bowmar Elementary / Report Number 020

201 Park Court, Suite B

Ridgeland, MS 39157

P 601.790.9432

F 888.281.0547

One Jackson Place, Suite 250

188 East Capitol Street

Jackson, MS 39201-2100

P 601.352.5411

F 601.352.5362

161 Lameuse Street, Suite 201

Biloxi, MS 39530

P 228.374.1409

F 228.374.1414

Contract Paul Jackson & Son

Date / Time 01 December 2020 / 11:30 PM

Weather / Temp Clear / 50 ° F

Est % Complete 50%

Sched Conformance +/- 00 days

Work in Progress Welding

Masonry Electrical

Present at Site Jimmy White, PJ&S

Paul Purser, DBA

Mason, electricians, and welders were all on site working. Block was being installed and has been installed up to 2 courses at the time of my

visit.

Steel has been installed as well as roof joists and decking for the front 2/3 of the addition. The remainder of steel awaits full installation of the

back CMU structural wall.

I met Jimmy White on the slab and we discussed work progress. He intends to pour concrete at sidewalks within the next few weeks. We looked at some potential issues with leaving the sidewalks un-poured at this stage of the progress, including wash out that has already begun at

corners of dig area.

We also walked the interior of the existing building and reviewed ceiling demo that has been performed in the gym and cafeteria areas. Making our way to the boiler room, Jimmy pointed out a plumbing and electrical conflict at the new panel location. He mentioned that Travis Altsman is

aware of the conflict and working towards a solution.

Items to Verify

Action Required

None

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – South Corner of Addition




Figure 2 – CMU installation is ongoing




Figure 3 – Roof Decking installed over ceiling joists



Figure 4 – Remainder of Steel work is awaiting CMU block installation



Figure 5 – Remainder of Steel work is awaiting CMU block installation



Figure 6 – West Corner of Addition



Figure 7 – SE side of Existing Glazing Installed




Figure 8 – Gymnasium Ceiling Removed



Figure 9 – Cafeteria Ceiling Removed



Figure 10 – Plumbing/Electrical Conflict (awaiting resolution)