

28 January 2021

18045-BOW Bowmar Elementary / Report Number 023

201 Park Court, Suite B

Contract Paul Jackson & Son

Ridgeland, MS 39157

Date / Time 26 January 2021 / 1:30 PM

P 601.790.9432

Weather / Temp Overcast / 68 ° F

F 888.281.0547

Est % Complete 70%

One Jackson Place, Suite 250

Sched Conformance +/- 00 days

188 East Capitol Street

Work in Progress Interior Service Work

Jackson, MS 39201-2100

Jimmy White, PJ&S

P 601.352.5411

James Brock, PJ&S

F 601.352.5362

Paul Purser, DBA

Observations

Arriving on site, I met Jimmy White (PJS) and James Brock (PJS) at the

161 Lameuse Street, Suite 201

rear of the school. They both mentioned that progress was being made but that some subs did have some issues with COVID-19 issues.

Biloxi, MS 39530 P 228 374 1409 At the addition, service workers were inside installing rough in materials.

P 228.374.1409 F 228.374.1414 Plywood blocking has been installed at steel studs. Some ducting has

been installed.

Items to Verify

Present at Site

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Exterior Progress



Figure 2 – Exterior Progress



Figure 3 – Exterior Progress



Figure 4 – Drainage Issues at Courtyard




Figure 5 – HVAC Ducting is Ongoing



Figure 6 – Plywood Blocking Installed



Figure 7 – Plywood Blocking Installed



Figure 8 – Plywood Blocking Installed




Figure 9 – HVAC Ducting is Ongoing



Figure 10 – Plywood Blocking Installed