

18 March 2021

18045-BOW Bowmar Elementary / Report Number 027

201 Park Court, Suite B

Paul Jackson & Son Contract

Ridgeland, MS 39157

18 March 2021 / 10:30 AM Date / Time

P 601.790.9432

Cloudy / 51 ° F Weather / Temp

F 888.281.0547

Est % Complete 70%

One Jackson Place, Suite 250

Sched Conformance +/- 00 days

188 East Capitol Street

Work in Progress

Storefront Installation **HVAC Demo and Install**

Jackson, MS 39201-2100

Electrical Work

P 601.352.5411

Stucco Work

F 601.352.5362

Drywall Finishing

161 Lameuse Street, Suite 201

Present at Site Jimmy White, PJS

Biloxi, MS 39530

James Brock, PJS

P 228.374.1409

Weekly Meeting Attendees

Paul Purser, DBA

Observations F 228.374.1414

Arriving on site, I met Jimmy White at the entry to the school. He was

finishing up the installation of a rumble strip at the ADA Parking Pad. We

walked in together and discussed progress.

Most interior HVAC units have been demoed, but pipes and hangers still

require removal and walls still need patching. Most new interior units

should be operational.

At the addition, storefront in quite far along and nearly complete. Stucco

work has begun. Finish work at drywall has also begun.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

James Brock / Jimmy White (PJS)

Chad Shealy / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Rumble Strip Installed at ADA Parking Pad



Figure 2 – HVAC Unit Installed at Office



Figure 3 – HVAC Unit Removal at Classroom nearly complete



Figure 4 – Installed Concrete



Figure 5 – Installed Concrete



Figure 6 – Installed Concrete



Figure 7 – Brick Washed



Figure 8 – Brick Washed



Figure 9 – Stucco Lathe Installed



Figure 10 – Stucco Lathe Installed



Figure 11 – Drywall Finishing in Progress



Figure 12 – Drywall Finishing in Progress



Figure 13 – Bathroom Drywall Installed



Figure 14 – Bathroom Drywall Installed



Figure 15 – Storefront at Connector Hall



Figure 16 – Storefront at Brick Corner



Figure 17 – Damaged Ceiling Grid IN cafeteria Requires Replacement




Figure 18 – Damaged Ceiling Grid IN cafeteria Requires Replacement