

28 May 2021

Date / Time

18045-BOW Bowmar Elementary / Report Number 030

201 Park Court, Suite B

Paul Jackson & Son Contract

Ridgeland, MS 39157

26 May 2021 / 2:00 PM

P 601.790.9432

Cloudy / 75 ° F Weather / Temp

F 888.281.0547

Est % Complete 70%

One Jackson Place, Suite 250

Sched Conformance +/- 00 days

188 East Capitol Street

Work in Progress None

Jackson, MS 39201-2100

Jimmy White, Paul Jackson & Son Present at Site

P 601.352.5411

Paul Purser, DBA

F 601.352.5362

Observations

They were preparing for ceiling grid installation at the hall. Also, VCT floor install was in progress. We looked over the VCT tile installation in one of the rooms and noted some areas that needed re-installation. Most of the work looks good, there were just a few touch-up areas.

On site, I met Jimmy White in the main corridor of the new addition.

Awnings at the exterior have also been installed.

161 Lameuse Street, Suite 201

Biloxi, MS 39530

P 228.374.1409

F 228.374.1414

Mr. White mentioned their schedule is right on track and that they are looking forward to getting into the main school this next week to

complete their remaining tasks.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

James Brock / Jimmy White (PJS)

Chad Shealy / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Roof Trim Replaced to Match



Figure 2 – Rear Exit Corridor; this area needs to be kept clean for egress from main building in case of an evacuation event.




Figure 3 – Above Ceiling Painted




Figure 4 – New VCT Installed



Figure 5 – ADA Bathroom Installed



Figure 6 – Door Panels Installed



Figure 7 – Millwork Installed



Figure 8 – Millwork Installed



Figure 9 – New VCT Installed



Figure 10 – New VCT Installed