

23 June 2021

18045-BOW Bowmar Elementary / Report Number 032

201 Park Court, Suite B

Contract

Paul Jackson & Son

Ridgeland, MS 39157

Date / Time

22 June 2021 / 12:30 PM

P 601.790.9432

Weather / Temp

Sunny / 90 ° F

F 888.281.0547

Est % Complete

80%

One Jackson Place, Suite 250

Sched Conformance

+/- 00 days

188 East Capitol Street Jackson, MS 39201-2100 Work in Progress

Glazing, painting, drywall install

P 601.352.5411

Present at Site

Paul Purser, DBA

F 601.352.5362

Observations O

On site, I met Ricky (PJS), Jimmy White's stand-in while on vacation. We reviewed work in classrooms 3,4,6,8 for a partial punch list to be issued so that the contractor can move furniture from hallways to these rooms.

161 Lameuse Street, Suite 201

Biloxi, MS 39530

DIIOXI, IVIS 57550

P 228.374.1409 F 228.374.1414

In the playroom, work on the new ADA ramp is coming along. Concrete is in place as well as drywall at our newly framed wall. A worker was in

this room as well cleaning newly installed glass.

At both hallway bathrooms in the main corridor, work is moving along with drywall installers putting in panels. Floor are being prepped throughout as well, but contractor is awaiting tile to be delivered (I was

told next Monday it should be in).

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)

Chad Shealy / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Stairs at newly installed ADA ramp



Figure 2 – Drywall installed at ADA ramp



Figure 3 – ADA ramp installed at Playroom



Figure 4 – Sock Duct installed at Playroom



Figure 5 – Sock Duct installed at Playroom



Figure 6 – Drywall Installed at Boys 30




Figure 7 – Plumbing installed at Girls 29



Figure 8 – Floor prep at classroom 24