

14 July 2021

18045-BOW Bowmar Elementary / Report Number 034

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

Contract Paul Jackson & Son  
Date / Time 14 July 2021 / 10:30 AM  
Weather / Temp Clear / 89 ° F  
Est % Complete 85%

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Sched Conformance +/- 00 days  
Work in Progress Floor Wax Installation, Plumbing Installation, Clean Up, Floor Installation, Drywall Finish and Paint  
Present at Site Jimmy White, PJS  
Paul Purser, DBA

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Observations Arriving on site, I entered the property from the main entrance. At the exterior of the main entry, caulking has been installed at concrete joints.  
Inside and upstairs, linoleum floor is being installed. Floor has been prepped in these areas as is typical throughout this project.  
Downstairs, workers are cleaning and waxing floors in many rooms. Fenestration installers are also at work throughout. Painters are finishing surfaces and performing touchups throughout.

Items to Verify None  
Action Required None

Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)  
Chad Shealy / Bill Sanderford (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)  
Tom Schaeffer / Will Grigg (M)  
Kevin Starks / Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)



Figure 1 – Caulking at New Concrete



Figure 2 – Caulking at New Concrete





Figure 3 – Caulking at New Concrete



Figure 4 – Auditorium is Being Used for Storage





Figure 5 – Floor Prep at Laminate Floor @ 2<sup>nd</sup> Floor



Figure 6 – Linoleum Floor Installation is Ongoing





Figure 7 – New Linoleum Floor @ 2nd Floor



Figure 8 – Existing Floor Condition @ 2<sup>nd</sup> Floor



Figure 9 – Floor Wax Installation is Ongoing in Some Rooms



Figure 10 – Tiled wall at Boys Room





Figure 11 – Sink on left in Boys is Crooked and Requires Adjustment



Figure 12 – Window Progress at Cafeteria Wall



Figure 13 – Wall Patch and Repair in Cafeteria



Figure 14 – New ADA ramps installed and Wood Finished





Figure 15 – Blind Installation is Ongoing



Figure 16 – Blinds Installed





Figure 17 – Doors Require Adjustment; Also stationary leaf requires flush bolt



Figure 18 – Gates Installed at Breezeway