

Architect's Field Report

201 Park Court, Suite B

01 June 2020

Date / Time

Ridgeland, MS 39157

18048-Redwood Elementary School / Report Number 002

P 601.790.9432 F 888.281.0547

Contract Harris Construction

29 May 2020 / 2:45 PM

One Jackson Place, Suite 250

Weather / Temp CI

188 East Capitol Street

Clear / 83 ° F

Jackson, MS 39201-2100

Est % Complete 1

1%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress Sidewalk Demo

Present at Site Michael Byrd, Harris Construction

161 Lameuse Street, Suite 201

Paul Purser, DBA

Biloxi, MS 39530 P 228.374.1409

F 228.374.1414

Observations

Arriving on site, I met Mr. Michael Byrd, HC, at the entrance. We

discussed the uncovered dirt and next steps in constructing our entry

ramp.

We walked the school to review ceiling grid and tile work that had been

performed.

At Teacher's Lounge E-113, we reviewed demolition of a plumbing wall that is indicated on our plans. The concern was brought up that if we removed the wall, we would expose hidden plumbing that is to remain to service fixtures on the other side of the wall. I instructed Mr. Byrd to leave wall in place and block the end of the wall for a finished look.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: David Harris / Michael Byrd (HC)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Ebony Batchelor / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Entry Demo Work



Figure 2 – Entry Demo Work



Figure 3 – New Ceiling Installation is Ongoing



Figure 4 – New Ceiling Installation @ Classrooms is Ongoing




Figure 5 – Ceiling Tile Replacement



Figure 6 – Ceiling Tile Replacement




Figure 7 – Library Ceiling Work



Figure 8 – Some Adjusting Required at the end of this Row at Ceiling Grid




Figure 9 – Auditorium Ceiling Replacement is Ongoing




Figure 10 – Hall Ceiling Replacement



Figure 11 – Plumbing to be Removed




Figure 12 – Wall to Remain to Conceal Plumbing



Figure 13 – Sidewalk Demo



Figure 14 – Sidewalk Demo