

## Architect's Field Report

201 Park Court, Suite B

04 September 2020

Ridgeland, MS 39157

18048-Redwood Elementary School / Report Number 007

P 601.790.9432

F 888.281.0547 Contract Harris Construction

Date / Time 02 September 2020 / 2:45 PM

One Jackson Place, Suite 250

188 East Capitol Street

Weather / Temp Partly cloudy / 92 ° F

Jackson, MS 39201-2100

Est % Complete 50%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress None

F 001.332.330.

Work in Frogress None

161 Lameuse Street, Suite 201

Present at Site

Biloxi, MS 39530 P 228.374.1409

F 228.374.1414

Arriving on site, I parked in the rear. I reviewed work performed at entry. The tops of walls have been smoothed with grinding and appear

uniform. There is some clean up needed from this work, specifically at

the stair nosing where concrete dust has accumulated.

Items to Verify

Observations

None

**Action Required** 

Clean Up Stair Nosing

Paul Purser, DBA

Remove Asphalt and Flashing at Canopies between Buildings D & B

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: David Harris / Michael Byrd (HC)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Ebony Batchelor / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Demo of Canopy still requires removal of asphalt & asphalt flashing



Figure 2 – Concrete Work at Entry



Figure 3 – Tops smoothed



Figure 4 – Some Clean up still required at Black Stair Nosing



Figure 5 – Front Entry Sidewalks Poured



Figure 6 – Wall Tops Smoothed



Figure 7 – Planter Filled



Figure 8 – Drainage Outlets at Planter