

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

21 July 2020

18050-South Park Elementary / Report Number 015

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Paul Jackson & Son  
Date / Time 21 July 2020 / 12:30 PM  
Weather / Temp Clear / 92 ° F  
Est % Complete 40%  
Sched Conformance + 00 days  
Work in Progress Floor Demo

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site Paul Purser, DBA

Observations Arriving on site, I entered at the main entry. Workers were demoing the front entry tile. Also, in this area, a worker was prepping tile with a grinder.

Tile demo is in progress at rejected tile in the new ADA bathroom.

At the addition, damp-proofing is in progress at the exterior CMU walls.

Items to Verify None

Action Required Re-adhere roll roofing at scuppers

Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Wes Gill (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Abigail Raper / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer / Brian Champlin / Tad Hoffpaur (SDG)



Figure 1 – Demoed Floor Tile



Figure 2 – Demoed Floor Tile



Figure 3 – Tile Grinding for Prep



Figure 4 – Tile Installed at Wall



Figure 5 – Floor Tile Installed; Tile rejected is being removed



Figure 6 – Damp-proofing at CMU



Figure 7 – Roofing at Cricket and New Roof



Figure 8 – Roofing at Cricket and New Roof



Figure 9 – Roofing Installed



Figure 10 – Roofing Installed



Figure 11 – Roof Drainage Outlet



Figure 12 – Roof Outlet; roll roofing needs to be re-adhered



Figure 13 – Corner Detail at Roof Curbs



Figure 14 – Corner Detail at Roof Curbs