

Architect's Field Report

201 Park Court, Suite B

02 October 2020

Date / Time

Ridgeland, MS 39157

18050-South Park Elementary / Report Number 020

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

29 September 2020 / 2:45 PM

One Jackson Place, Suite 250

Weather / Temp

188 East Capitol Street

Clear / 73 ° F

Jackson, MS 39201-2100

Est % Complete 55%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress None

161 Lameuse Street, Suite 201

Present at Site

Wes Gill, PJS

Biloxi, MS 39530

Observations

Paul Purser, DBA

P 228.374.1409 F 228.374.1414 for the day. We walked the addition and reviewed the brick mock-up wall. Grid work is complete and awaiting above ceiling inspections from our engineers. Windows have also been installed at the upper wall

Arriving on site, I met Wes Gill in the lay down area. He was closing up

sections of the rear addition.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Wes Gill (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Abigail Raper / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Brian Champlin / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Lay Down Area



Figure 2 – Mock Up Brick Wall; there's some unevenness in the mortar color



Figure 3 – Ceiling Grid Work



Figure 4 – Ceiling Grid Work



Figure 5 – Ceiling Grid Work




Figure 6 – Ceiling Grid Work



Figure 7 – Ceiling Grid Work




Figure 8 – Ceiling Grid Work




Figure 9 – Ceiling Grid Work



Figure 10 – Sewer Line Install



Figure 11 – Windows Installed at CMU Wall




Figure 12 – Electrical Subpanel Installed