

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

21 October 2020

18050-South Park Elementary / Report Number 021

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 20 October 2020 / 12:45 PM
Weather / Temp Clear / 77 ° F
Est % Complete 55%
Sched Conformance + 00 days
Work in Progress Painting
Awning Structure Install
Sidewalk Concrete Install
Parapet Install

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414


Present at Site Wes Gill, PJS
Paul Purser, DBA

Observations Arriving on site, I met Wes Gill at the rear addition. He was installing blocking at the roof parapet. Per our discussion, the project is progressing according to schedule.

Inside, flooring has been installed and painters were at work touching up. Base at the new floor is of good workmanship, however it does not have preformed corners as required in specifications.

Items to Verify None
Action Required Install Preformed Corners

Report By:

2020.10.2
14:34:08 1
'00'05- 

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Wes Gill (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Abigail Raper / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Brian Champlin / Tad Hoffpaur (SDG)



Figure 1 – Awning Columns Set



Figure 2 – Sidewalk Install



Figure 3 – Sidewalk Install



Figure 4 – Sidewalk Install



Figure 5 – Sidewalk Install



Figure 6 – Sidewalk Install



Figure 7 – Back Corner of Addition



Figure 8 – Back Corner of Addition



Figure 9 – Base Installed; preformed corners are required at inside and outside corners per spec



Figure 10 – Interior Door Panels Installed



Figure 11 – VCT Flooring Installed



Figure 12 – Ceiling Tile Installed



Figure 13 – Crooked Vent at Ceiling Requires Correction



Figure 14 – Preformed Corners Required