

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

19 May 2020

18053-Vicksburg Junior High School / Report Number 010

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 18 May 2020 / 2:00 PM
Weather / Temp Clear / 79 ° F
Est % Complete 10%
Sched Conformance + 00 days
Work in Progress Mechanical Work
Painting
Interior Demo

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Jeff Porter, Paul Jackson & Son
Paul Purser, DBA

Observations Arriving on site, I noted site work at the entry addition. Inside the entry, laborers were performing some limited demo in the prior office area. Mechanical laborers were working in the west hall in class rooms. Some painters were in the south hall applying paint.

Items to Verify None

Action Required None

Report By:

Paul Purser, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Tad Hoffpauir (SDG)



Figure 1 – Asphalt Cut for 12" RCP



Figure 2 – Dirt Work at ne Entry Addition



Figure 3 – Demoed Asphalt



Figure 4 – Is this our Roof Drain?



Figure 5 – Sediment should be Continuous around Grate Per Civil Drawings



Figure 6 – Foundation Formwork



Figure 7 – Cast in Place Wall, Poured



Figure 8 – Roof and Wall @ Corridor E-226




Figure 9 – Demo at E-202B



Figure 10 – Wall Cavity @ E217-A



Figure 11 – Wall Cavity @ E217-A



Figure 12 – Wall Cavity @ E217-A




Figure 13 – Paint is ongoing in Southern Hall



Figure 14 – Lower Concrete Wall Removed