

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

21 October 2020

18053-Vicksburg Junior High School / Report Number 022

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Paul Jackson & Son  
Date / Time 20 October 2020 / 2:30 PM  
Weather / Temp Clear / 81 ° F  
Est % Complete 48%  
Sched Conformance + 00 days  
Work in Progress CMU Block Work  
Metal Frame Installation

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414


Present at Site Jeff Porter, PJS  
Paul Purser, DBA

Observations Arriving on site, I noted work performed at slab. CMU block work is ongoing. Jeff Porter was on site working on installation of metal door frame at existing school entry. Preparation has been made for concrete pour at the upper landing of the existing stair.

Items to Verify None

Action Required None

Report By:

2020.10.2  
16:19:42 1  
'00'05- 

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer / Tad Hoffpaur (SDG)



Figure 1 – NE View Looking SW



Figure 2 – Block Work at NE Corner



Figure 3 – Block Cavity at Footing



Figure 4 – Block Work Ongoing



Figure 5 – Block Work Ongoing



Figure 6 – Block Work Ongoing



Figure 7 – Block Work Ongoing



Figure 8 – Block Work Between Columns at Existing Stair



Figure 9 – Block Work Between Columns at Existing Stair



Figure 10 – Block Work Between Columns at Existing Stair



Figure 11 – Slab Prep at Upper Landing of Existing Stair



Figure 12 – Block Work at Stair



Figure 13 – Scaffold at CMU Work



Figure 14 – SE View Looking NW