

Architect's Field Report

201 Park Court, Suite B

31 December 2020

Ridgeland, MS 39157

18053-Vicksburg Junior High School / Report Number 026

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

29 December 2020 / 1:30 PM

One Jackson Place, Suite 250

Weather / Temp Clear / 64 ° F

188 East Capitol Street

Jackson, MS 39201-2100

Est % Complete 50%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Biloxi, MS 39530

F 228.374.1414

Work in Progress Masonry

Present at Site Jeff Porter, PJS

Paul Purser, DBA

161 Lameuse Street, Suite 201

Observations

Date / Time

Arriving on site, I noted that brick work is nearing completion. Masons

P 228.374.1409

were still on site, finishing up the work, but for the most part, our brick

veneer has been installed.

At the interior, some duct work has been installed. Roof drains have also

been connected and a temporary drain to the exterior is installed

currently.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Austin Stults / Jeff Porter / Kipp Ready (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – East Elevation




Figure 2 – East Entry



Figure 3 – North Elevation



Figure 4 – Typical Window Jamb Detail



Figure 5 – South Elevation



Figure 6 – South Elevation




Figure 7 – Interior Admin Area




Figure 8 – Interior Hall



Figure 9 – Interior Admin Area




Figure 10 – Interior Hall Paint is Ongoing



Figure 11 – Interior Hall Paint is Ongoing



Figure 12 – Interior Hall Paint is Ongoing