

Architect's Field Report

201 Park Court, Suite B

06 February 2021

Date / Time

Ridgeland, MS 39157

18053-Vicksburg Junior High School / Report Number 028

P 601.790.9432

F 888.281.0547 Contract Paul Jackson & Son

04 February 2021 / 3:00 PM

One Jackson Place, Suite 250

Weather / Temp Overcast / 65 ° F

188 East Capitol Street

Jackson, MS 39201-2100

Est % Complete 60%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress Electrical

Present at Site

Jeff Porter, PJS

161 Lameuse Street, Suite 201

Observations

Paul Purser, DBA

Biloxi, MS 39530 P 228.374.1409

F 228.374.1414

Arriving on site, I entered from the new addition's entrance. Continued

409

rough of services is ongoing here. At the new concession area, CMU has $\,$

been installed and looks in good order.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Storage Area at Parking Lot



Figure 2 – East Elevation



Figure 3 – Test Sealant Colors at Exterior Brick




Figure 4 – Electrical Rough In is Ongoing



Figure 5 – Block work at new concessions area



Figure 6 – Block work at new concessions area



Figure 7 – Block work at new concessions area



Figure 8 – Block work at new concessions area



Figure 9 – Block work at new concessions area



Figure 10 – Block work at new concessions area




Figure 11 – Addition Entry from Main building



Figure 12 – Upstairs Storage Outside of Library



Figure 13 – Roof Awaiting Tie In



Figure 14 – Roof Awaiting Tie In