

Architect's Field Report

201 Park Court, Suite B

12 March 2021

Ridgeland, MS 39157

18053-Vicksburg Junior High School / Report Number 030

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

One Jackson Place, Suite 250

11 March 2021 / 9:00 AM

188 East Capitol Street

Weather / Temp Partly cloudy / 75 ° F

Jackson, MS 39201-2100

Est % Complete 65%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress Service Installation

Service Installations
Asphalt Preparations

161 Lameuse Street, Suite 201

Present at Site

Observations

OAC Meeting Attendees

Roofing

Biloxi, MS 39530 P 228.374.1409

Paul Purser, DBA

F 228.374.1414

Asphalt preparation is ongoing. Curbs at the East Lot Entry need some

rework per Civil. Compaction is also to be verified after Ice event.

Interior Service work is ongoing. Electricians are roughing in still and

HVAC is ongoing.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Southeast Looking NW



Figure 2 – Parking Lot Compacted (per OAC meeting requires additional verification of compaction after Weather Event)




Figure 3 – Interior Service work is Ongoing



Figure 4 – Interior Service work is Ongoing



Figure 5 – Cast Iron Boots Installed



Figure 6 – Grading near Roof Edge




Figure 7 – Roof Work at Remodeled Wall



Figure 8 – Roof Work at Remodeled Wall



Figure 9 – Interior at Concessions




Figure 10 – Elevator work to wrap up ASAP