

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

28 May 2021

18053-Vicksburg Junior High School / Report Number 033

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Paul Jackson & Son  
Date / Time 26 May 2021 / 12:30 PM  
Weather / Temp Cloudy / 75 ° F  
Est % Complete 70%  
Sched Conformance + 00 days  
Work in Progress None

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site Jeff Porter, PJS  
Paul Purser, DBA

Observations On site, concrete installers were cleaning and preparing areas for concrete. They have performed work at the connecting sidewalk between the field house and the main school.

Inside, ceiling grid has been installed throughout including the library. Electricians were on site as well.

Parapet trim has been installed at the upper wall of the main façade and roofers were also attending to other work as well.

Awning work has also begun.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer / Tad Hoffpauir (SDG)



Figure 1 – Roof Work is nearing completion



Figure 2 – Roof Trim Installed at parapet



Figure 3 – Metal Awning Install has begun



Figure 4 – Metal Awning Install has begun



Figure 5 – Gypsum Ceiling Installed



Figure 6 – Ceiling Grid Install at Entry



Figure 7 – Drywall Repair at Work Room



Figure 8 – Ceiling Grid installed at Hall



Figure 9 – Exit Doors Installed



Figure 10 – Storefront; will interior of porch area be raised for final floor level to match threshold?



Figure 11 – Library ceiling needs finishing at end where window shows above new ceiling



Figure 12 – New Ceiling in Library



Figure 13 – New Sidewalk Base



Figure 14 – Sidewalk Base