

Architect's Field Report

201 Park Court, Suite B

14 July 2021

Date / Time

Ridgeland, MS 39157

18053-Vicksburg Junior High School / Report Number 037

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

14 July 2021 / 11:30 AM

One Jackson Place, Suite 250

Weather / Temp

Sched Conformance

Clear / 90 ° F

188 East Capitol Street Jackson, MS 39201-2100

Est % Complete 85%

P 601.352.5411

+ 30 days

F 601.352.5362

F 228.374.1414

Work in Progress

Masonry Install, Electrical Work, Concrete Forming

Present at Site

Jeff Porter, PJS Paul Purser, DBA

161 Lameuse Street, Suite 201 Biloxi, MS 39530

Observations

On site, masons were working on our new fence. Installation is ongoing

P 228.374.1409

but workers are slowly making progress.

Inside, millwork has been installed. Installation is in progress and some

adjustments are still needed.

Prep at the storefront entry at the upper floor is ongoing. Some leveling has been performed, but it appears that this is a process that may take several pours. Ceiling work has been completed in the library area

outside of this entrance at the 3rd floor.

Site work is ongoing. Workers were installing forms for our new

sidewalk.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Austin Stults / Jeff Porter / Kipp Ready (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Masonry is Ongoing




Figure 2 – Masonry is Ongoing



Figure 3 – Awning Installation is Ongoing



Figure 4 – New Millwork Installed



Figure 5 – New Millwork Installed



Figure 6 – New Millwork Installed




Figure 7 – Upper Millwork Doors Require Adjustment



Figure 8 – Leveling at Up Floor in Ongoing for new Storefront Entrance



Figure 9 – Site Work is Ongoing



Figure 10 – Site Work is Ongoing



Figure 11 – New Ceiling in Library



Figure 12 – New Ceiling in Library