

Architect's Field Report

201 Park Court, Suite B	23 June 2021
ZUT PAIK COULL, SUILE B	

18056-Warren Central Junior High School / Report Number 025

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Ridgeland, MS 39157

P 601.790.9432 F 888.281.0547

161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414

10030-Warren central Julior High School / Report Number 025	
Contract	Paul Jackson & Son
Date / Time	22 June 2021 / 2:00 PM
Weather / Temp	Sunny / 91 ° F
Est % Complete	80%
Sched Conformance	+ 00 days
Work in Progress	Awning Install
Present at Site	Paul Purser, DBA
Observations	Awning work is ongoing and nearing completion at the front entry. The awning appears straight and in good order.
	Inside, there is a leak at the cafeteria east wall. Is the roof fully flashed at this point?
Items to Verify	None
Action Required	None
Report By:	

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Tim Wilson / Kipp Ready (PJS) Chad Shealy / Christi Kilroy (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Candy Failor (DBA) Brandon McKay / Austin Newell (WGK) Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS) Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Awning Installation



Figure 2 – Awning Installation



Figure 3 – damaged mud-work due to moisture



Figure 4 – A leak is apparent here; is there a solution yet?



Figure 5 – A leak is apparent here; is there a solution yet?



Figure 6 – Electronic Holds Installed and Operational