

Architect's Field Report

201 Park Court, Suite B

01 July 2021

Date / Time

Weather / Temp

Work in Progress

Ridgeland, MS 39157

18056-Warren Central Junior High School / Report Number 026

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

One Jackson Place, Suite 250

30 June 2021 / 1:00 PM

188 East Capitol Street

Partly cloudy / 91 ° F

Jackson, MS 39201-2100

Est % Complete 85%

P 601.352.5411

Sched Conformance + 30 days

F 601.352.5362

Awning Install, Paint/Mud Finishing

Present at Site Paul Purser, DBA

161 Lameuse Street, Suite 201

Observations

Arriving on site, I entered through the front entry. Awning work here is

Biloxi, MS 39530

nearing completion. Stucco, here, is complete as well.

P 228.374.1409 F 228.374.1414

At the interior, the temporary wall between cafeteria sections has been

removed. Work in this area is ongoing.

Finish work at the 2nd floor corridor is being performed. The connector has been opened and temporary walls have been removed. Ensure security on site at this connector and that doors here are lockable and

being locked overnight.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP

Dale | Bailey, an Association

cc: Austin Stults / Tim Wilson / Kipp Ready (PJS)

Chad Shealy / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – North Building Facade



Figure 2 – Awning Installation; paint at steel work is ongoing and requires more coverage




Figure 3 – Stucco Work at Entry Complete




Figure 4 – Temporary Divider Removed at Cafeteria




Figure 5 – Corridor Addition Opened Up




Figure 6 – Corridor Addition Opened Up



Figure 7 – Gutters Tied into Drainage at North Façade of Corridor at $2^{\rm nd}$ Floor



Figure 8 – Gutters Tied into Drainage at North Façade of Corridor at 2nd Floor