

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

28 January 2021

18057-Warrenton Elementary / Report Number 008

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract KT Builder
Date / Time 26 January 2021 / 1:00 PM
Weather / Temp Overcast / 68 ° F
Est % Complete 85%
Sched Conformance + 00 days
Work in Progress None

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Paul Purser, DBA

Observations Arriving on site, I reviewed clean up at the rear ADA ramp installation. There is tracked dirt on sidewalks that needs to be cleaned off as soon as the contractor is able. Also, disturbed soil at the ramp needs to be seeded/sodded to keep from further erosion due to rain events.

Work is still pending at the steel and concrete ADA ramp at the exterior classroom.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Hunter McNeer / Walt Swider (KT)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Ebony Batchelor / Candy Failor (DBA)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Tracked Dirt at Existing Sidewalk



Figure 2 – ADA Ramp Clean Up



Figure 3 – ADA Ramp Clean Up (note disturbed dirt needs seed or sod to keep from further erosion)



Figure 4 – ADA Ramp Clean Up (note disturbed dirt needs seed or sod to keep from further erosion)



Figure 5 – ADA Ramp Clean Up (note disturbed dirt needs seed or sod to keep from further erosion)



Figure 6 – ADA Ramp Clean Up (note disturbed dirt needs seed or sod to keep from further erosion)



Figure 7 – ADA Ramp Clean Up (note disturbed dirt needs seed or sod to keep from further erosion)



Figure 8 – ADA Ramp Clean Up (note disturbed dirt needs seed or sod to keep from further erosion)