

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

16 October 2019

18059-AOI Academy of Innovation / Report Number 004

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Century Construction  
Date / Time 15 October 2019 / 4:00 PM  
Weather / Temp Drizzle / 69 ° F  
Est % Complete 2%  
Sched Conformance +/- 00 days  
Work in Progress None

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site Paul Purser, DBA

Observations I arrived and it had just cleared up from a hard rain. No one was on site. Entry Gates were open. Some wash out has occurred at the job site trailer entry.

I walked the site. Pad work has been performed at the upper slab section since our last visit. New fencing up at NE Corner of project.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner  
Dale | Bailey, an Association

cc: Wilson Little (CC)  
Chad Shealy / Shaquita Burke (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Will Commarato / Candy Failor (DBA)  
Brandon McKay / Jason Kackley / Al Guynes (WGK)  
Chris Green / Larry Scott (TPS)  
Jerry Montgomery (SM)



Figure 1 – New Materials stored on Site



Figure 2 – Wash out at Job Site Trailer Entry



Figure 3 – Pad Development at Upper Slab



Figure 4 – Northeast corner Looking W



Figure 5 – New Fence at NE Corner



Figure 6 – New Fence



Figure 7 – North Center Entry Looking SE



Figure 8 – North Center Entry Looking S



Figure 9 – North Center Entry Looking SW



Figure 10 – North West of Center Looking S (Note Wash Out)



Figure 11 – North West of Center Looking SW



Figure 12 – Northwest Corner of Site Looking S



Figure 13 – West Edge of Site Looking East



Figure 14 – Southwest Corner of Project Looking E



Figure 15 – South End of Project



Figure 16 – South Center of Project



Figure 17 – Parking Area



Figure 18 – Entry Gate at North Side of Project



Figure 19 – Stored Material