

Architect's Field Report

201 Park Court, Suite B

06 November 2019

Ridgeland, MS 39157

18059-AOI Academy of Innovation / Report Number 007

P 601.790.9432 F 888.281.0547

Contract Century Construction

05 November 2019 / 1:30 PM

One Jackson Place, Suite 250

161 Lameuse Street, Suite 201

Weather / Temp

Clear / 71 ° F

188 East Capitol Street Jackson, MS 39201-2100

Est % Complete 2%

P 601.352.5411

Sched Conformance +/- 00 days

F 601.352.5362

GeoPier Install, Foundation Work, Dirt Work

Joey Moore, Century Construction

Present at Site

Work in Progress

Date / Time

Wilson Little, Century Construction

Entora

Wilson Little, Century Constructio Entergy Crew

Dirt Work Crew GeoPier Crew Foundation Crew

P 228.374.1409 F 228.374.1414

Biloxi, MS 39530

Paul Purser, DBA

Observations

Arriving on site, I walked the upper slab and reviewed Isolation

excavations and rebar installation.

I met Wilson Little and Joey Moore, who mentioned enthusiasm about Entergy getting their work done so that Century could begin foundation

work.

Wilson Indicated that upper slab isolation footings would be done first

and that Geo Pier work would be finishing up soon.

Items to Verify None
Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Wilson Little (CC)

Chad Shealy / Shaquita Burke (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Will Commarato / Candy Failor (DBA) Brandon McKay / Jason Kackley / Al Guynes (WGK)

Chris Green / Larry Scott (TPS)
Jerrry Montgomery (SM)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Isolation Footing (typical)



Figure 2 – Isolation footing with Beam (confirm concrete coverage of rebar per Section 032000.3.01/D/5 is adequate)



Figure 3 – Excavated Footing



Figure 4 – Confirm Concrete Coverage between rebar and Earth



Figure 5 – Geo Pier Drill out and Install



Figure 6 – North Entry Looking SE



Figure 7 – North Entry Looking S



Figure 8 – North Entry Looking SW



Figure 9 – Low Point in Silt Fencing



Figure 10 – Dirt Compaction on South Parking Area