

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

09 January 2020

18059-AOI Academy of Innovation / Report Number 015

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Century Construction

Date / Time 09 January 2020 / 9:45 AM

Weather / Temp Clear / 52 ° F

Est % Complete 32%

Sched Conformance + 02 days

Work in Progress Foundation Work – Formwork

Present at Site  
Foundation Crew  
AOC Meeting Participants  
Paul Purser, DBA

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Observations I arrived prior to our monthly meeting and walked site. I noted no major changes in the East section of the upper building.

Moving westward, I saw that Foundation Waterproofing had begun. A base layer had been applied to the foundation concrete wall up to 8 feet on the east (dirt) side. A large amount of form work was still in place and currently being removed.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner  
Dale | Bailey, an Association

cc: Wilson Little / Joey Moore / Allison Wood (CC)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Will Commarato / Candy Failor (DBA)  
Brandon McKay (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Jerry Montgomery (SM)



Figure 1 – Red Steel Erected



Figure 2 – Safety Wire In Place at 2<sup>nd</sup> Floor



Figure 3 – Foundation (Dirt Side)



Figure 4 – Bolts for Steel Structure in Place @ Lower Level



Figure 5 – Formwork Removed @ Exterior of Foundation Wall



Figure 6 – Mel-Rol Sheet Drainage Assembly



Figure 7 – Bitumen Self Adhering Sub Sheet with Fabric Drainage Plain in Place



Figure 8 – North Entry Looking ESE



Figure 9 – North Entry Looking S



Figure 10 – North Entry Looking WSW