

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

16 January 2020

18059-AOI Academy of Innovation / Report Number 016

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Century Construction  
Date / Time 15 January 2020 / 4:15 PM  
Weather / Temp Drizzle / 70 ° F  
Est % Complete 32%  
Sched Conformance + 02 days  
Work in Progress Foundation Work – Formwork  
Steel Erection

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site Foundation Crew  
Steel Crew  
Billy Burwell, Century  
Paul Purser, DBA

Observations Arriving, met Mr. Billy Burwell. We walked the site. Mr. Burwell mentioned that they've spent the last few days pumping water out of East Building in preparation for substrate install.

I noted formwork being set at the east building section. At the west building section, steel is currently being installed.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner  
Dale | Bailey, an Association

cc: Wilson Little / Joey Moore / Allison Wood (CC)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Will Commarato / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Jerry Montgomery (SM)



Figure 1 – Red Steel Erected



Figure 2 – Upper East Building Site Condition



Figure 3 – Formwork Bracing @ Upper Building



Figure 4 – Formwork @ Upper East Building for Topping Slab



Figure 5 – Lower Level Progress, Steel Erected



Figure 6 – Steel @ Lower Level Footings



Figure 7 – North Entry Looking ESE



Figure 8 – North Entry Looking S



Figure 9 – North Entry Looking WSW



Figure 10 – Northeast Storm Sewer Set