

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

27 August 2020

18059-AOI Academy of Innovation / Report Number 044

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Century Construction

Date / Time 26 August 2020 / 5:00 PM

Weather / Temp Partly cloudy / 90 ° F

Est % Complete 60%

Sched Conformance + 68 days

Work in Progress Welding Installation
Drywall Finishing
HVAC Installation

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Paul Purser, DBA

Observations Arriving on site, I entered the building from the bottom floor at the west building. At the kitchen, the commercial vent hood has been set in place. Concrete board and drywall is also being hung in this space.

At the second level, drywall is being finished. Mudwork at the gym is taped and ongoing. Many classrooms are partially mudded and some public spaces have mud work begun.

At the North elevation of the eastern most section of building, there is a glass panel that is off-colored. This Panel requires replacement.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Wilson Little / Joey Moore / Allison Wood (CC)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Will Commarato / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Jerry Montgomery (SM)



Figure 1 – Metal Siding Installed



Figure 2 – Door Trim Detail



Figure 3 – Mechanical Room



Figure 4 –Vent Hood Set In Place



Figure 5 – 2nd Floor at Corridor 154



Figure 6 – Gym Drywall Mud Work



Figure 7 – Versatile Teaching Space 120



Figure 8 – Versatile Teaching Space 220



Figure 9 – HVAC Ducting Is On Going



Figure 10 – TWR 202



Figure 11 – East Elevation Glass Installed



Figure 12 – North Elevation of East Structure



Figure 13 – North Elevation Metal Siding Installation is Ongoing; at the second level furthest panel to the right, glass is off colored and requires replacement



Figure 14 – North Elevation at West Structure