

Architect's Field Report

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	21 November 2020 18059-AOI Academy of Innovation / Report Number 050
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Contract Century Construction Date / Time 20 November 2020 / 2:30 PM Weather / Temp Clear / 62 ° F Est % Complete 65% Sched Conformance + 68 days Work in Progress Panel Installation Stucco Work Awning Installation
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Present at Site Paul Purser, DBA Observations Installers were putting together the Vitruvian Man at the North Elevation. Also, at the North elevation, awning installers were at work installing the roof covering at the main drop-off's awning. Stucco workers have built scaffolds in this area and have begun installing metal lather in preparation for stucco install. On the inside, Painters were continuing there work throughout.
	Items to Verify None Action Required None.
	Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Wilson Little / Joey Moore / Allison Wood (CC)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Will Commarato / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Jerry Montgomery (SM)



Figure 1 – The Vitruvian Man



Figure 2 – Panel Installation is Ongoing



Figure 3 – Awning Covering Installation is Ongoing



Figure 4 – Awning Covering Installation is Ongoing



Figure 5 – Stucco work has begun at the main Entrance



Figure 6 – Stucco work has begun at the main Entrance



Figure 7 – Metal Paneling and Curtain Wall at the Entrance



Figure 8 – Main Entry Foyer



Figure 9 – Millwork at Main Entrance Check In



Figure 10 – Ceiling Paint Work



Figure 11 – Main Lobby



Figure 12 – Paint Work is Ongoing



Figure 13 – Paint Work is Ongoing



Figure 14 – Partition Wall Installation is Ongoing



Figure 15 – Partition Wall Installation is Ongoing



Figure 16 – Partition Wall Installation is Ongoing



Figure 17 – Painted Ceilings



Figure 18 – Paint at Gym