

## Architect's Field Report

201 Park Court, Suite B

31 December 2020

Ridgeland, MS 39157

18059-AOI Academy of Innovation / Report Number 052

P 601.790.9432 F 888.281.0547

Contract **Century Construction** 

29 December 2020 / 2:15 PM

One Jackson Place, Suite 250

161 Lameuse Street, Suite 201

Clear / 64 ° F Weather / Temp

188 East Capitol Street

Est % Complete 85%

Jackson, MS 39201-2100

Sched Conformance + 74 days

P 601.352.5411 F 601.352.5362

Paint Work

Work in Progress

Date / Time

Ceiling Gird Installation

Finish Electrical Finish Plumbing

Mechanical

Biloxi, MS 39530 P 228.374.1409

**Curtain Wall Installation** 

F 228.374.1414

Joey Moore, CC

Paul Purser, DBA

Observations

Present at Site

Arriving on site, I noted that sod at the exterior has been delivered and is awaiting installation. Entering the building from the lower west entry,

I see that paint and ceiling work is still ongoing. Ethernet cable has been

pulled to closets as well.

Items to Verify

None

**Action Required** 

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Wilson Little / Joey Moore / Allison Wood (CC)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Will Commarato / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Jerrry Montgomery (SM)

dalepartners.com baileyarch.com

Architects Who Know Education




Figure 1 – Sod is on Site and Ready to Install




Figure 2 – Curtain Wall Installation is Ongoing



Figure 3 – Concrete Rework at Drop Off Entry



Figure 4 – Cafeteria Paint and Ceiling Install is Ongoing




Figure 5 – Cafeteria Paint and Ceiling Install is Ongoing




Figure 6 – Paint and Ceiling Install is Ongoing Throughout



Figure 7 – Ceiling Grid Install is Ongoing Throughout




Figure 8 – Communication Cabling Installed



Figure 9 – Ceiling Grid Work Ongoing



Figure 10 – Glass Installed at Moveable Partitions